

BERRYBANK DEVELOPMENT Pty. Ltd.



29/01/2020 Weekly Construction Report

SUMMARY OF BOP TASKS	
LAST WEEK	THIS WEEK
 WTG 27 & 28- working around installation Trenching cables in CG 2 & 1. CG 3 & 4 pulled into switch room culvert Drainage and rehabilitation Fencing and gate installation LG1750 crane moved from WTG 27 to WTG 28 	 Rehabilitation works in CG 6, 7 and 8 Drainage works in CG 6, 7 and 8 HV terminations in substation CG 1 & 2 trenching to substation Joint pits in CG 7 & 8
WTG COMPONENTS DE	ELIVERIES LAST WEEK
 WTG38: 3 Blades, T1 and T2, Hub and Drivetrain arrived WTG41: 2 Blades, T2 and Hub arrived WTG2, 3, 6 & 10: Nacelle arrived 	 WTG27: T1 and T2 pre-installation, T3 and T4, Drivetrain arrived WTG28: T1 and T2 pre-installation WTG38: Cooler Top installation
WTG COMPONENTS C	CURRENTLY ON-SITE
 Anchor Cage: 43 of 43 (43 Installed) Switchboard: 43 of 43 (43 Installed) Tower Sections: 57 of 172 (16 Installed) Nacelle: 31 of 43 	 Drive Train: 15 of 43 Cooler Top: 29 of 43 Hub: 31 of 43 Blades: 74 of 129
ON-SITE SUBSTATION WORKS	OFF-SITE SUBSTATION WORKS
 Installation of switchyard equipment Connection of conductor Construction of culvert Construction of building footings Construction of transformers discharge pipe Cable trenching and lying up to the switch room 	 Footings excavation and reinforcement Concrete pour for footings Steel equipment installation Equipment being stored Culvert construction
IRANSMISSI	ON LINE WORKS
Pegging of the pole's location	Access to poles definition

On-Site Substation



Off-Site Substation

